

## Inspectierapport voertuig

Rapportnr.: MC-IR-58310 | Voertuig-ID: 58310 | Uitgiftedatum: 2026-08-24

|                                        |                      |                                                             |
|----------------------------------------|----------------------|-------------------------------------------------------------|
| ADVERTENTIE<br>2026 Yamaha Tracer 9 GT | TYPE<br>Motorfiets   | STATUS<br>Beschikbaar                                       |
| MERK<br>Yamaha                         | MODEL<br>Tracer 9 GT | BOUWJAAR<br>2026                                            |
| CONDITIE<br>Gebruikt                   | LOCATIE<br>Denmark   | GARANTIE-INFORMATIE<br>Inspection available before handover |

|                                   |                                |                                  |
|-----------------------------------|--------------------------------|----------------------------------|
| 100%<br>Dealer reviewed inventory | Review<br>Dealer certification | Prepared<br>Handover preparation |
|-----------------------------------|--------------------------------|----------------------------------|

## IDENTITEIT EN DOCUMENTATIE

| CONTROLEPUNT                 | BEVINDING / NOTITIE                  | RESULTAAT     |
|------------------------------|--------------------------------------|---------------|
| Voertuig-ID                  | 58310                                | GEVERIFIEERD  |
| Voertuigtype                 | Motorfiets                           | GEVERIFIEERD  |
| VIN / chassisnummer          | Te bevestigen bij overdracht         | IN AFWACHTING |
| Registratiedatum             | 2026-02-01                           | BEOORDEELD    |
| Original registration papers | Available for dealer handover review | GEVERIFIEERD  |

## MECHANISCHE INSPECTIE

| CONTROLEPUNT          | BEVINDING / NOTITIE                                                 | RESULTAAT    |
|-----------------------|---------------------------------------------------------------------|--------------|
| Engine start and idle | Cold start, idle stability and visible leak check                   | GOEDGEKEURD  |
| Engine size           | 890 cm <sup>3</sup>                                                 | GEVERIFIEERD |
| Transmission          | inspection_report.value_transmission_Schaltgetriebe                 | GEVERIFIEERD |
| Powertrain response   | Throttle response, clutch/drive engagement and abnormal noise check | GOEDGEKEURD  |
| Cooling and fluids    | Oil, coolant, brake fluid and visible hose condition checked        | GOEDGEKEURD  |

VEILIGHEID EN RIJKLAARHEID

| CONTROLEPUNT             | BEVINDING / NOTITIE                                                       | RESULTAAT   |
|--------------------------|---------------------------------------------------------------------------|-------------|
| Brakes                   | Front/rear braking response and visible disc/pad condition checked        | GOEDGEKEURD |
| Tyres / wheels           | Tyre condition, wheel alignment indicators and visible rim damage checked | GOEDGEKEURD |
| Suspension / steering    | Steering movement, fork/shock condition and bearing play check            | GOEDGEKEURD |
| Lights / horn / controls | Operational control check completed                                       | GOEDGEKEURD |
| Mileage                  | 1639                                                                      | VASTGELEGD  |

UITERLIJK EN VOORBEREIDING

| CONTROLEPUNT         | BEVINDING / NOTITIE                              | RESULTAAT     |
|----------------------|--------------------------------------------------|---------------|
| Exterior color       | Niet gespecificeerd                              | IN AFWACHTING |
| Body panels / frame  | Visible condition and preparation notes reviewed | GOEDGEKEURD   |
| Dealer preparation   | Prepared before customer handover                | GEVERIFIEERD  |
| Dealer certification | Dealer review required before final handover     | IN AFWACHTING |

LEVERINGSGEREEDHEID

| CONTROLEPUNT           | BEVINDING / NOTITIE                                                  | RESULTAAT   |
|------------------------|----------------------------------------------------------------------|-------------|
| Pickup readiness       | Customer pickup can be scheduled after admin confirmation            | GEREED      |
| Road delivery          | Covered or trailer delivery can be arranged where available          | BESCHIKBAAR |
| International delivery | International export support available                               | BESCHIKBAAR |
| Handover documents     | Contract, invoice and inspection report prepared for customer review | GEREED      |

LISTING EQUIPMENT AND NOTES

|                                                                                                                                                                                                   |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Make: Yamaha Model: Tracer 9 GT Body type: Sonstige Condition: Used First registration: 02/2026 Mileage: 1.639 km Engine: 890 cm³ Power: 87 kW (118 PS) Fuel: Benzin Transmission: Schaltgetriebe |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

INSPECTOR / HANDOVER SIGN-OFF

PREPARED BY

MotoComply ApS inspection team

FINAL HANDOVER CONFIRMATION

\_\_\_\_\_

MotoComply ApS inspection report for Vehicle ID 58310. Prepared from available listing and inspection information for customer review before handover.